



INTERNATIONAL ATOMIC ENERGY AGENCY
UNITED NATIONS EDUCATIONAL, SCIENTIFIC AND CULTURAL ORGANIZATION
INTERNATIONAL CENTRE FOR THEORETICAL PHYSICS
I.C.T.P., P.O. BOX 586, 34100 TRIESTE, ITALY, CABLE: CENTRATOM TRIESTE



H4.SMR/638-25

College on Medical Physics:
Imaging and Radiation Protection

31 August - 18 September 1992

Overview of Radiological Accidents

P. Ortiz-Lopez

International Atomic Energy Agency
Vienna, Austria

The Radiological Accident in Goiânia



INTERNATIONAL ATOMIC ENERGY AGENCY, VIENNA, 1988

GOIÂNIA - BRAZIL

A private radiotherapy institute
moved to new premises

A Cs-137 teletherapy unit remained
in the old premises

THE LICENSING AUTHORITY WAS NOT NOTIFIED

The old premises were subsequently
partially demolished

THE Cs-137 THERAPY UNIT BECAME
TOTALLY INSECURE

TWO PEOPLE ENTERED THE PREMISES
REMOVED THE SOURCE ASSEMBLY
FROM THE IRRADIATION HEAD
AND TOOK IT HOME

4 PERSONS DIED
(ACUTE RADIATION SYNDROME)

112.000 persons monitored
249 contaminations
110 cytogenic studies

3.800 drums (200L) waste
1.400 metal boxes (5 Tons)
10 shipping containers
3500 m³

MEXICO (CIUDAD JUÁREZ)

A medical center purchased a Co-60
Teletherapy unit.

The unit remained stored for several
years without being installed
(It had been introduced into the
country without compliance with
import requirements).

THE SOURCE ASSEMBLY WAS REMOVED
FROM THE UNIT. THE CAPSULE OF THE
SOURCE WAS PERFORED.

THE SOURCE TOGETHER WITH SOME
OTHER PARTS OF THE EQUIPMENT
WAS SOLD TO A SCRAP SHOP.

THERE MUCH OF THE EXISTING SCRAP
WAS CONTAMINATED. IT WAS SOLD
TO DIFFERENT COMPANIES, AMONG
THEM A STEEL COMPANY, WHICH
MANUFACTURES RODS AND
SIMILAR PRODUCTS.

IT WAS DETECTED IN THE USA, WHERE
RODS (CONTAMINATED) WERE TRANSPORTED
TO.

6000 TONES OF RODS WERE PRODUCED
3000 SETS OF RODS FOR JETKS

4000 persons were radiation exposed
2% > 0,25 Sv

5 persons: 3 to 7 Sv (2 months)

- 17000 buildings (where contaminated rods might have been used) were monitored
- decision was taken to demolish 814 buildings
- 16000 m³ of contaminated earth were accumulated in a repository built for the purpose

ACCIDENTS IN RADIOTHERAPY

CHRONOLOGY OF AN ACCIDENT

05-12-1990.-Radiotherapy staff operating the accelerator note that it does not work: absence of electron beam.

They communicate the failure to the technician of the company who was performing a maintenance to a Co-60 teletherapy machine, at the same hospital.

The technician carries out a first revision of the accelerator, and postpones the work 07-12 (the 6th is a holiday).

07-12-1990.-After his intervention, the display on the control panel shows always 36 MeV regardless of the selected energy (7,10 13 MeV), but there is an electron beam. That was interpreted as a jam of the needle at 36 MeV.

10-12-1990, Monday. The treatment of patients resumes.

20-12-1990. The staff informs the Radiation Protection Department about the incorrect energy display. The treatment are stopped. The physicians start correlating this fact with the poor tolerance and bad reactions observed in some patients.

21-12-1990. A dosimetry of the beam is carried out and it is found that the energy of the electron beam is always 36 MeV regardless of the energy selected on the control panel (7, 10 or 13 MeV).

The maintenance company is notified. It sends technicians to repair the failure and to make a general revision of the accelerator.

Technical description

The path (curvature) of the electron beam is a function of its energy and the intensity of the magnetic field generated by deviation coils. $f(E, I_c)$.

For a given electron energy, there is only one coil intensity I_c , which can achieved the correct curvature. Vice versa for a given I_c there is only one electron energy for which the path is correct.

Under normal conditions, for each energy selected I_c , the proper I_c is automatically set by the accelerator.

It is admitted that there was a short circuit in the control unit of the coils so that Ic was always the maximal one.

- 10 -

Annex 1 European Radiotherapy Accidents Reported after
1st January 1986 as know to EFOMP Accident Reporting scheme on 15th May 1992

Country	Approximate Dates	Number of Injured	Nature of Injury	Investigation	Probable Cause	EFOMP Accident
UK	1983	1	high morbidity (£455,000 damages)	?	Prescription error + communication failure	-
(W) Germany	6.86-3.87	96	Increased morbidity possibly deaths	Criminal investigation (Failure to report)	Error in ⁶⁰ Co dose tables (7% overdose)	-
UK	2.88-7.88	205	*	Health authority Enquiry	Error in ⁶⁰ Co dose rate (25% overdose)	-
UK	6.88-7.89	22	increased morbidity or recurrence rate	Health Authority	Failure of label system for implant sources (¹³⁷ Cs) (-20 to + 10% over/under	-
Spain	12.90	27	increased morbidity or recurrence rate	at national level	Maintenance error + communication failure	9.91
UK	1982-1991	989	increased risk of recurrence	Health Authority Enquiry	Inadequate QA of new procedure (5-30% underdose)	No
Czech.	1987	1	death probably attributable	At national level	treatment in non-clinical accelerator mode	-

Negative reports or reports only of minor accidents have been received from Norway, Poland, Russia and Turkey.

NRC INFORMATION NOTICE 91-02
BRACHYTHERAPY

- ① The Medical Physicist noted that there were two instead of three Cs-137 sources in the storage safe drawer.
Failure to return all brachytherapy sources promptly after removal.
The source was lost. A contributing factor \Rightarrow the source was coloured ^{White} easy to lose among bed linen... landfill
- ② Ir-192 endobronchial treatment
25 seeds of 3.5 mCi each in a nylon ribbon. It became dislodged from the catheter.
The duty nurse taped the end to the patient's face. The charge nurse noticed... 1,032 rem to face
Corrective actions: 282 rem to eyes
removal of the nurse from caring brachytherapy patients
training + written examination
- ③ Nylon ribbon with 7.2 mCi Ir-192 was cut into two pieces. Inventory
One piece was found 22 days later within a crack between the carpeting and the wall.

INCIDENTS AND ACCIDENTS IN
BRACHYTHERAPY

LOSS OF CONTROL OF Ir-192 SOURCES (3 Cases during hospitalization).

A PATIENT WAS DISCHARGED FROM THE HOSPITAL WITH AN Ir-192 INCORPORATED.

RADIOACTIVE MATERIAL WAS USED IN NON-LICENSED HOSPITALS. THEY WERE CARRIED BY THE RADIOTHERAPIST FROM ANOTHER (LICENSED) HOSPITAL. THE UNAUTHORIZED USE OCCURRED WITHOUT SUFFICIENT RADIATION PROTECTION MEASURES, AND WITHOUT PERSONAL DOSIMETERS FOR THE NURSES.

INCIDENTS AND ACCIDENTS IN BRACHYTHERAPY

ONE PATIENT WAS MOVED FROM ONE HOSPITAL TO ANOTHER WITH Ir-129 SOURCES IMPLANTED, WITHOUT NOTIFICATION TO THE PERSONAL RECEIVING THE PATIENT. ASSISTANCE WAS GIVEN TO THE PATIENT DURING ONE DAY, IGNORING THAT HE HAD RADIOACTIVE MATERIAL.

SEVERAL AFTERLOADING Cs-137 EQUIPMENT WERE PURCHASED AND STORED IN HOSPITALS FOR YEARS WITHOUT ANY SURVEILLANCE.

INCIDENTS IN BRACHYTHERAPY (RADIUM-226)

SINCE THE BEGINNING OF THE USE OF RADIUM SOURCES FOR RADIOTHERAPY, MORE THAN 100 SETS OF SOURCES WERE USED BY DIFFERENT SPECIALISTS: (RADIOLOGISTS, DERMATOLOGISTS, GYNECOLOGISTS...)

AT THAT TIME THERE WAS NO REGULATION, NOR REGULATORY CONTROL.

THE ORIGINAL OWNERS DIED IN MANY OF THE CASES. AFTER A LONG AND TEDIOUS PROCESS OF SEARCHING MORE THAN 110 SETS OF RADIUM SOURCES WERE DISPOSED OF IN SAFE STORAGE BY THE AUTHORITIES.

SOME 15% OF THE SETS OF SOURCES PRESENTED LEAKAGE. TWO OF THEM CAUSED CONTAMINATION OF LARGE PROPORTIONS (BUILDING, GARDEN)

INCIDENTS IN BRACHYTHERAPY (RADIUM-226)

11 OF THESE SETS WERE INCOMPLETE (RELATED TO THE ORIGINAL PURCHASE DOCUMENTS), ANOTHER 8 SETS COULD NOT BE CHECKED FOR COMPLETENESS BECAUSE OF LACK OF DOCUMENTS.

INCIDENTS IN BRACHYTHERAPY
(RADIUM-226)

11 OF THESE SETS WERE INCOMPLETE (RELATED TO THE ORIGINAL PURCHASE DOCUMENTS), ANOTHER 8 SETS COULD NOT BE CHECKED FOR COMPLETENESS BECAUSE OF LACK OF DOCUMENTS.

NRC- INFORMATION NOTICE- 90-59
J-131

- ① Yearly control (whole body scan)
4.89 mCi I-131 Lactation
Synthetic hormone prescribed to the child
with follow-up.
- ② Confusion :
Instead of thyroid scan \Rightarrow whole body scan
300 μ Ci I-123 \Rightarrow 3 mCi I-131
No written request from the n.m. physician
was required
- ③ Confusion: Instead of
ectopic thyroid evaluation \Rightarrow
post-thyroidectomy neck scan was
requested
100 μ Ci \Rightarrow 1 mCi I-131
- ④ Ectopic thyroid evaluation
50-100 μ Ci \Rightarrow 4.5 mCi I-131
List of dosage was wrong
- ⑤ 4-5 weeks pregnant
Failure to ask
15 μ Ci of I-131
total body \sim 2. to 4 mrem

SAFETY CULTURE

1.- Good practice is essential but not sufficient.

2.- There is a requirement to go beyond the strict implementation of a good practice, so that all duties related with safety are carried out:

Correctly

with alertness

with due thought

with full knowledge

sound judgement

and a proper sense of accountability

The highest level of safety is achieved only when every one is dedicated to the common goal:

Individual awareness of the importance of safety

knowledge and competence conferred by training, instruction and self-education

commitment at senior management level

motivation through leadership

supervision including audits and review practices

responsibility through formal assignment and description of duties

The SAFETY CULTURE involves all levels:

Policy level,

commitment of the management

response of individuals