


QC in Diagnostic Radiology

- PURPOSE : To ensure continuing production of diagnostic images with optimum quality, using minimum necessary dose to the patient.
- FREQUENCY: QC should include checks and test measurements on all parts of the imaging system at intervals not exceeding one year.
- UK practice for most common DR equipment:
- Radiographic (X-ray tubes) once per year



Main steps for a QC survey in Diagnostic Radiology

- General X-ray tube & generator assessment
- Image quality assessment
- Specific parameters assessment
- Quality Control protocols





QC equipment for Radiography



- Dosimeter (ion.ch.)
- kVp detector (non-invasive) CALIBRATED !
- Oscilloscope (with memory)
- (Timer, mA meters)
- Aluminium plates (4x1mm+2x0.5mm)
- Collimator/beam alignment tool (cassette)
- Focal spot test tool (film in envelope)
- (Densitometer, Sensitometer)

X-ray tube and generator main tests


- X-ray beam filtration
- Dose output consistency, kV/mA influence
- kVp consistency, accuracy, ripple
- Timer consistency, accuracy
- X-ray beam/light beam alignment
- Radiation leakage of tube housing
- Focal spot size assessment
- Automatic Exposure System performance

QC of the X-ray tube/generator

- The X-ray field must be collimated to the smallest reasonable size.
- All measurements must be performed at the middle of the X-ray field.








Total X-ray filtration <u>must not be less</u> than:

- <u>0.5 mm</u> of Al (or 0.03 mm Mo) for mammography
- <u>1.5 mm</u> of Al for equipment using voltage up to 70 kVp (most often Dental Radiology)
- <u>2.0 mm</u> of Al for equipment producing above 70kVp and up to 100 kVp
- <u>2.5 mm</u> of Al for equipment producing voltages above 100 kVp (most of the Diagnostic Radiology X-ray equipment)
- LBD filtration Al plates MUST be fixed!

Dose Output/kVp/Time Consistency

- Min 4 exposures with identical parameters 100*(st.dev)/(average) for all measurements
- Separate calculations for Dose, kVp, Time
- In the case below : Dose consist. = 3.2%; kVp consist. = 0.6%; Time consist. = 0%


Focus	Set kV	SetmA	Set Time			MeasT	Meas exp	Air kerma
	(kV)	(mA)	(ms)	(mAs)	(kV)	(ms)	(mR)	(mGy)
В	80	200	100	20	82	105	104	0.90
В	80	200	100	20	83	105	106	0.92
В	80	200	100	20	83	105	106	0.92
В	80	200	100	20	83	105	105	0.91




kVp accuracy and Spec.Dose = F(kV) Linearity


- Min 4 measurements with varia kVp 100*(mean error)/(real value)
- In the case below kVp accur. = 3.4%
- Specific Dose : Dose/mAs (mGy/mAs) @ ...kV
- Linearity graph: X-kV² Y-(mGv/mAs)


							1 00(011)-	100
Focus	Set kV	Set mA	Set Time		Meas kV	Meas T	Meas exp	
	(kV)	(mA)	(ms)	(mAs)	(kV)	(ms)	(mR)	(mGy)
В	60	200	100	20	62	101	59	0.51
В	80	200	100	20	83	105	98.5	0.86
В	100	200	100	20	104	103	151	1.31
В	120	200	100	20	123	103	224	1.95






SetkV	SetmA	Set Time	SetmAs	Meas kV	Meas T	Meas exp	Air kerma	Spec.Output
(kV)	(mA)	(ms)	(mAs)	(kV)	(ms)	(mR)	(mGy)	mGy/mAs
80	25	100	2.5	83	107	18.4	0.16	0.064
80	300	100	30	84.7	105	198	1.72	0.057
80	500	100	50	90	103	305	2.65	0.053
80	200	20	4	83	19	20.5	0.18	0.045
80	200	400	80	83	390	440	3.82	0.048
80	200	800	160	83	780	814	7.07	0.044











X-ray tube housing leakage


 X-ray tube housing radiation leakage - tested with closed collimator, tube housing surrounded with cassettes and heavy (~100 kV) exposure (keep the films!)













Automatic Exposure Control


- Tested with various attenuators for all AEC fields
- Measured: cassette entrance dose and film optical density (for best results these are very similar)
- AEC guard timer : Cut-off time (max. dose)


+	
1015 EW 10015	E .7 +
00	Limit T


*AEC - field	Attenuator	Set kV	Read ms	mAs	Optic.Dens	Meas exp
&dose set	(mm Cu)	(kV)	(ms)	(mAs)	(D)	(mR)
L	1.6	80	7	7	1.55	0.96
R	1.6	80	6	7	1.45	0.88
С	1.6	80	5	6	1.3	0.76
All	1.6	80	6	6	1.5	0.88
L	3.2	80	52	52	1.8	1.12
R	3.2	80	47	47	1.75	1.02
С	3.2	80	40	40	1.7	0.88
All	3.2	80	45	45	1.75	0.98




















Other QC tests

- Acceptance testing of new equipment
- Service engineer (radiographer)
- Documentation
- Check all operating modes and accessories
- Radiation safety
- Electrical safety
- Mechanical safety

Automatic QA protocols with EXCEL


- Raw data page
- Calculative page (hidden)
- Result page
- Image quality and graphics pages
- Statistical page
- Summary and Recommendation page
- Additional protocols for AEC and other specific X-ray systems

Gould 450 s			MDH electro				al storage os	cincecepe
1		1			· · · · · ·		FDD(cm)=	100
Focus	SetkV	SetmA	SetTime	SetmAs	Meas kV	Meas T	Meas exp	Air kerma
	(kV)	(mA)	(ms)	(mAs)	(kV)	(ms)	(mR)	(mGy)
В	60	200	100	20	62	101	59	0.51
В	80	200	100	20	83	105	98.5	0.86
В	100	200	100	20	104	103	151	1.31
В	120	200	100	20	123	103	224	1.95
F	50	100	200	20	50	202	46	0.40
F	70	100	200	20	73	205	101	0.88
F	90	100	200	20	88	202	167	1.45
F	110	100	200	20	111	204	221	1.92
В	80	200	100	20	82	105	104	0.90
В	80	200	100	20	83	105	106	0.92
В	80	200	100	20	83	105	105	0.91
В	80	25	100	2.5	83	107	18.4	0.16
В	80	300	100	30	84.7	105	198	1.72
В	80	500	100	50	90	103	305	2.65
В	80	200	20	4	83	19	20.5	0.18
В	80	200	400	80	83	411	440	3.82
В	80	200	800	160	83	780	814	7.07
		Half Va	lue Layer M	easuremer	nts are sho	wn below		
B+0mm AI	80	200	100	20			114	0.99
B+0mm AI	80	200	100	20			110	0.96
B+1mm Al	80	200	100	20			83.5	0.73
B+2mm AI	80	200	100	20			67.1	0.58
B+3mm AI	80	200	100	20			50.9	0.44
B+4mm AI	80	200	100	20				#VALUE!


FDD(cm)=	100							
Meas exp	Air kerma		Meas'		mGy/mAs		%age kV	
(mR)	(mGy)	Meas kV	kV^2	mGy/mAs	perkV^2	grad'	Accuracy	Accuracy
59	0.51	62	3844	0.025636	6.67E-06	5.64E-06	3.333333	
98.5	0.86	83	6889	0.042798	6.21E-06	5.81E-06	3.75	
151	1.31	104	10816	0.06561	6.07E-06	7.35E-06	4	
224	1.95	123	15129	0.097328	6.43E-06		2.5	
46	0.40	50	2500	0.019987	7.99E-06		0	
101	0.88	73	5329	0.043885	8.24E-06	8.45E-06	4.285714	
167	1.45	88	7744	0.072562	9.37E-06	1.19E-05	-2.22222	
221	1.92	111	12321	0.096025	7.79E-06	5.13E-06	0.909091	
104	0.90	82	6724	0.045188	6.72E-06			
106	0.92	83	6889	0.046057	6.69E-06			
105	0.91	83	6889	0.045623	6.62E-06			
18.4	0.16	83	6889	0.063958	9.28E-06			
198	1.72	84.7	7174.09	0.057354	7.99E-06			
305	2.65	90	8100	0.053009	6.54E-06			
20.5	0.18	83	6889	0.044536	6.46E-06			-
440	3.82	83	6889	0.047795	6.94E-06			2.7
814	7.07	83	6889	0.04421	6.42E-06			-2.
114	0.99	IVL mm of A	% trans					#VALUE
110	0.96	1	100					
83.5	0.73	2	74.5535714					
67.1	0.58	3	59.9107143					
50.9	0.44	4	45.4464286					
	#VALUE!	5	#VALUE!					

Parameters		Expected	Measured	Assessmer
Radiography Mode		+		
Beam/LBD Alignemen		<1	<1	Accept
Bucky centering	displacement (cm)	<1	<1	Ассерт
Bucky centering	displacement (cm)	<1	<1	
Focus size (mm)	Broad Focus-(BF)	1	1X1	Accept
	Fine Focus-(FF)	0.6	0.6x0.6	Accept
O'put consistency(BF)	(%) inconsist.	<5	3.2	Normal
O'put var'n with mA(BF		<10	9.49	Normal
O'put var'n with kV (BF			4.2	Normal
Specific O'put-80kV(BI			42.74	Normal
Lin.Grad.with kV^2(BF)	(mGy/mAs/kV^2)		6.27E-06 15	
O'put var'n with kV (FF)	Linearity (%)		8.4	Normal
Specific O'put-80kV(FF	(uGy/mAs) @ 1m		57.47	Normal
Lin.Grad.with kV^2(FF)	(mGy/mAs/kV^2)		8.48E-06 40	
kVp consistency (BF)	(%) inconsist.	<5	0.6	Good
kVp accuracy (BF)	(%) inaccuracy	-10 <a<10< td=""><td>3.4</td><td>Good</td></a<10<>	3.4	Good
kVp accuracy (FF)	(%) inaccuracy	-10 <a<10< td=""><td>0.7</td><td>Good</td></a<10<>	0.7	Good
	Stdev.	10-21410	2.31	
kVp var'n with mA (BF)	(%) variation	<10	4.25	Good
Ripple at ~ 100 kV(BF)	+/- kVp ampl.		5	Accept
Timer consistency (BF	(%) inconsist.	<5	0.00	Good
Timer accuracy (BF)	(%) inaccuracy	-10 <a<10< td=""><td>-1.58</td><td>Good</td></a<10<>	-1.58	Good
	Stdey	1051310	3.96	
First Half Value Layer	(mm of Al eq')		2.7	Accept
Inferred Total Filtration	(mm of Al eq')	>2.5	2.6	Accept
Labelling	 			Accept
Stated filtration	(mm of Al eg')	2.5		Ассерг
Stated Total Filtration	(mm of Al eq')			
Calcul. max. leakage	(mGy/h)@1m	<1		Accept

Hospital/Clinic: Brook Hospital Unit type : Overcouch Department : X-ray Generator/Manuf. Philips Room/Unit: 3b Type : Defat/sool Date of QA survey : 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS The V-ray generator and table perform well. However, the X-ray beam is about 1cm displaced from the lightbeam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next roufine visit.	Department: Xray Generator/Manuf. Philips Rom/Unit: 3b Type: DR37/500 Date of OA survey: 22/3/93 Reference no.: BX063.633 Date of OA survey: 22/3/93 Reference no.: BX063.633 The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the X-ray beam is about 1cm displaced from the service engineer on his next However, the X-ray beam is about 1cm displaced from the service engineer on his next However, the X-ray beam is about 1cm displaced from the service engineer on his next However, the X-ray beam is about 1cm displaced from the service engineer on his next However, the X-ray beam is about 1cm displaced from the service engineer on his next However, the X-ray beam is about 1cm displaced from the service engineer on his next Howevev	Radiol	ogical Pr	otection	and Q	uality A	Assuran	ce Repo	ort
Department: X-ray Generator/Manuf.: Philips Room/Unit: 3b Type: INR 2550 Date of QA survey: 22/3/83 Reference no.: BXOB30.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray generator and tube perform well. However, the X-ray generator and tube perform well. However, the x-ray generator and tube perform well.	Department: Xray Generator/Manuf. Philips Rom/Unit: 3b Type: DR37/500 Date of Q4 survey: 22/3/93 Reference no.: BXOB38.033 Date of Q4 survey: 22/3/93 Reference no.: BXOB38.033 The Xray generator and tube perform well. However, the Xray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the Xray beam is about 1cm displaced from the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of the service engineer on his next to reduce the test of								
Department: X-ray Generator/Manuf.: Philips Room/Unit: 3b Type: DR37/500 Date of QA survey: 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on this next	Department: Xray Generator/Manuf. Philips Rom/Unit: 3b Type: DR37/500 Date of Q4 survey: 22/3/93 Reference no.: BXOB38.033 Date of Q4 survey: 22/3/93 Reference no.: BXOB38.033 The Xray generator and tube perform well. However, the Xray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the Xray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the Xray generator and tube perform well. However, the Xray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. However, the Xray generator and tube perform well. <td></td> <td></td> <td>l</td> <td></td> <td></td> <td></td> <td></td> <td></td>			l					
Image: Type: Destination Room/Unit: 30 X:Tube / Type: Str/500 Date of Q survey: 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next	Type: DR37/500 Rom/Unit: 3b XTube / Type: SR0.2550 Date of Q survey: 22/3/83 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next involve visit. Report compiled by: Report compiled by:	Hospital/Clinic:	Brook H	ospital		Unit type	9: T	Overcouch	
Image: Type: Destination Room/Unit: 30 X:Tube / Type: Str/500 Date of Q survey: 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next	Type: DR37/500 Rcom/Unit: 3b XTube / Type: SR250 Date of QA survey: 22/3/83 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next rourine visit. Report compiled by: Report compiled by: Report compiled by:	Department :	X-ray		·	Generat	i or/Manuf.:	Philips	
Boom/Unit: 30 X-Tube / Type: SRO 25 50 Date of QA survey: 22/3/83 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about from displaced from the light beam of LBD in longitudinal direction. We would advise grout the bing this to the attention of the service engineer on his next	Room/Unit: 3b X-Tube / Type: [SR0 25 50 Date of QA survey: 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS The X-ay generator and tube perform well. However, the X-ay beam is about 1 cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next is a strain of the service engineer on his next			1		1			
Date of QA survey: 22/3/93 Reference no.: BXOB3B.033 SUMMARY AND RECOMMENDATIONS SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. The X-ray generator and tube perform well. However, the X-ray beam is about from displaced from the light beam of LBD in longitudinal direction. We would advise go tube bring this to the attention of the service engineer on his next	Date of QA survey: 22/3/93 Reference no.: BXOB38.033 SUMMARY AND RECOMMENDATIONS The X-ray generator and bible perform well. The X-ray generator and bible perform well. However, the X-ray beam is about 1 cm displaced from the light beam of LBD in borgitudinal direction. We would advise you the bring this to the attention of the service engineer on his next routine visit.	Room/Unit:	3b			X-Tube	/ Type:	SRO 25 50	
SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. However, the X-ray beam is about 1cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next	SUMMARY AND RECOMMENDATIONS The X-ray generator and tube perform well. The X-ray generator and tube perform well. However, the X-ray beams insolution and the service of the service engineer on his next incurrence visit.								
The X-ray generator and tube perform well. However, the X-ray beam is about 1 cm displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next	The X-ray generator and tube perform well. The X-ray peems about 1 or displaced from the light beam of LBD in longitudinal direction. We would advise you the bring this to the attention of the service engineer on his next routine visit. Report compiled by:	Date of QA surv	ey: 22/3/93			Referen	ce no.:	BXOB3B.03	13
				e perform we					
Dr. S.D. Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
Dr. S.D. Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
Dr. S.D. Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
Dr. 5.D. Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
Dr. S.D. Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
Dr. S.D.Tabakov		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			
		direction. We w	ould advise y	ou the bring	splaced fro this to the a	ttention of			



Effectiveness of Quality Control in Radiography S Tabakov, M Stoeva



Often Hospital management accepts Quality Control (QC) of X-ray equipment as just a necessity linked to specific Regulations.

This might reflect in a superficial attitude to the QC tests linked mainly to "bureaucratic" collection of QC records.





Our study shows the effect of regular QC tests on the X-ray equipment performance and image quality, based on long term statistics, and compared with a period when no QC tests had been made

QC statistics made on the basis of :

- 63 X-ray generators&tubes (surveyed over 3 years) - from 1992-1995 (no QC have been carried out to these equipment for some 2 years before 1992)


-During the following 5 years 12 of those equipment have continued to be surveyed and analysed


- All equipment had been in use for less than 15 years


- 27 new X-ray generators&tubes have been surveyed and analysed over 3 years (1997-2000)


- All equipment has been surveyed with identical tests (IPEM and Emerald) and all data presented to the X-ray service

- The analysed parameters (statistics with SPSS package) are presented on the slides to follow









B Column


SEM SD


significant. However


observing equipment


positive reaction.


without defects shows slow

































Output variation with mA:


in new X-ray equipment does not show reaction of stabilising the parameter














Conclusions

- Without regular QC all parameters of X-ray systems deteriorate (pre 1991 data)
- Regular QC maintains the consistency of X-ray systems parameters within specification
- More frequent QC would have a quick positive effect on the improvement of the less stable parameters and therefore - on the overall X-ray equipment performance.

